

# Winds Damage Navy TH-73 Training Helicopters at Whiting Field



By Richard Burgess, Senior Editor

ARLINGTON, Va. – A strong wind that swept through Naval Air Station Whiting Field caused damage more than three dozen new TH-73 Thrasher training helicopters earlier this month, according to a Navy spokesman.

The following statement was issued by the Commander, Naval Air Training Command (CNATRA):

“On May 13, at approximately 10:35 a.m. CST, a significant weather event involving high winds up to 71 knots (gusting) caused damage to 41 TH-73 Thrasher helicopters assigned to Training Air Wing (TAW) 5. No injury to personnel occurred during the incident and there has been no reported damage to

any TH-57 Sea Ranger or T-6 Texan II aircraft positioned on the flight line. All aircraft were parked aboard Naval Air Station Whiting Field during the incident. The full extent of the resources needed to restore the fleet has not yet been finalized, however, repairs are not expected to exceed a month. No operational impact to the CNATRA mission is expected due to the availability of CNATRA's fleet of TH-57 Sea Ranger helicopters that remain undamaged."

The TH-73A, built by Leonardo's AgustaWestland Philadelphia Corp., is a military version of the Leonardo TH-119. The TH-73A was procured by the Navy to replace the Bell TH-57 Sea Ranger with the role of training rotary-wing and tilt-rotor pilots for the U.S. Navy, Marine Corps, and Coast Guard. The TH-73A was first delivered to TAW-5 in August 2021 and began training pilots in September 2022.

The Navy has ordered a total of 130 TH-73As. The Thrasher fleet is expected to complete replacement of the TH-57B/C during fiscal 2025 and serve through 2050, according to the Navy.