

F-35B Crashes in New Mexico En Route Test Assignment



ATLANTIC OCEAN (Oct. 18, 2023) U.S. Marine Corps Maj. Alex Horne, assigned to Air Test and Evaluation Squadron (VX) 23, conducts flight operations from the Royal Navy aircraft carrier HMS Prince of Wales (R09) in the Atlantic Ocean, Oct. 18, 2023. (U.S. Navy photo by Kyra Helwick)

By Richard R. Burgess, Senior Editor

ARLINGTON, Va. – An F-35B Lightning II strike fighter crashed shortly after takeoff from Kirtland Air Force Base, New Mexico, on May 28. The pilot ejected and was hospitalized with serious injuries.

The Marine Corps F-35B was en route to deliver to Edwards Air Force Base, California, for assignment to test duties. The aircraft was flying from the Lockheed Martin factory in Fort Worth, Texas, for delivery to Edwards.

According to press reports, the pilot was an Air Force officer assigned to the Defense Contract Management Agency's Fort Worth office.

Marine Operational Test and Evaluation Squadron One, headquartered at Marine Corps Air Station Yuma, Arizona, has a detachment at Edwards Air Force Base for F-35 test and evaluation.

Rep. Rob Wittman, chairman of the Tactical Air and Land Forces subcommittee of the House Armed Services Committee issued a statement on the mishap:

"I am incredibly grateful to the first responders who promptly aided the pilot after this crash and relieved to hear the pilot is in stable condition. I am praying for the pilot and their family as they undergo treatment for serious injuries.

"Any crash of our military aircraft is of utmost concern. While we know that expanding F-35 test capacity is the first step to fundamental F-35 transformation, this incident exacerbates the already urgent need to expand it. That's why I authored an amendment in this year's National Defense Authorization Act to increase F-35 test capacity by 50%, ensuring that the U.S. military can accelerate tests associated with our nation's largest defense acquisition program.

"This incident will undoubtedly cause a technical setback for F-35 modernization and warrants an extensive and thorough investigation to determine the exact cause of this crash."